


SKODA Octavia: 1FRV698

Vinnumber:	TMBJJ9NEXE0068615	Versionname:	OCTAVIA COMBI Elegance
First Registrationdate:	4/10/2013	Fiscalpower:	DSG 150PK Aut.
Expertise Mileage:	151063	Power Kw:	110
Bodytype:	Break	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1712
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2045,40
-------------------	---------

Door F R, Bad repair, Acceptable	0,00
----------------------------------	------



Alloy rim R R, Damaged, E - Replace

235,20



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Interior, Smell, Ozone treatment 152,58

No pictures to display

Floor covering F L, Burned, Smart repair 64,32



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Broken, Le - Replace and paint 735,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bad repair, Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bad repair, Acceptable 0,00



Door R R, Bad repair, Acceptable 0,00



Luggage space cover, Damaged, E - Replace 240,00



Sill outer R, Bump(s), LI - Repair and paint (complete) 406,50

