



## VOLKSWAGEN Touran: 1JEZ239

Vinnnumber:	<b>WVGZZ1TZFW035817</b>	Versionname:	<b>TOURAN Trendline BMT St&amp;St 7pl.105PK</b>
First Registrationdate:	<b>28/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>193812</b>	Power Kw:	<b>77</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1716</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Type of Tow bar	<b>Tow bar removable</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>195/65/15/81 T Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Fulda: 6 mm</b>	Re.R.	<b>Fulda: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------











Total cost ex VAT	<b>1331,42</b>
Tailgate, Bump(s), PDR - Knock out without painting	<b>63,00</b>



Door F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Roof pillar L, Bump(s), PDR - Knock out without painting	<b>82,80</b>
--	--------------

	Reflector, Damaged, E - Replace	55,00
	Trunk lid covering R, Scratch(es), E - Replace	125,00
	Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Door F R, Bump(s), PDR - Knock out without painting	63,00
	Seat cover F R, Stain, Cleaning	12,50
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Windscreen, Stone chip(s), E - Replace	487,20
	Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
	Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>		
	Rocker panel inner R R, Bump(s), LI - Repair and paint (complete)	115,56

*No pictures to display*