



BMW 3: 1DJT243			
Vinnumber:	WBA3D91010F401202	Versionname:	3 BER 316d 116PK
First Registrationdate:	5/06/2012	Fiscalpower:	
Expertise Mileage:	81985	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4719
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	









Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/50/17/98 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment	
Total cost ex VAT	2065,67
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------

	Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
	Tailgate, Chemical polution, LI - Repair and paint (complete)	301,68
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
	Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete)	115,56