



| MERCEDES A: 1HPK387                |                          |              |                       |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnnumber:                        | <b>WDD1760111V028412</b> | Versionname: | <b>A 160 CDI 90PK</b> |
| First Registrationdate:            | <b>5/09/2014</b>         | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>111497</b>            | Power Kw:    | <b>66</b>             |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Dark Grey</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>             |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1622</b>           |
| Number of doors:                   | <b>5</b>                 |              |                       |
| Number of seats:                   | <b>5</b>                 |              |                       |
| Number head rests:                 | <b>5</b>                 |              |                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                       |
| Category:                          | <b>Passenger Car</b>     |              |                       |
| Oil level:                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                       |

| Options                        |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| Windows electric F             | Luggage cover                 |
| Windows electric R             |                               |
| Steering wheel multifunctional |                               |
| Radio multimedia               |                               |
| Type of headlighting:          | <b>Headlighting Halogen</b>   |
| Type of GPS:                   | <b>GPS big screen color</b>   |
| Type of Lining:                | <b>Lining fabrics</b>         |
| Type of climate control:       | <b>Manual climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                 | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                    | <b>OK</b> |                     |            |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres:  | <b>205/55/16/91 T LightMetal</b> |                       |       |                       |
|                | Fr.L.                            | <b>Uniroyal: 5 mm</b> | Fr.R. | <b>Uniroyal: 5 mm</b> |
|                | Re.L.                            | <b>Uniroyal: 6 mm</b> | Re.R. | <b>Uniroyal: 6 mm</b> |

| Assistance equipment |            |            |            |
|----------------------|------------|------------|------------|
| Repair kit           | <b>Yes</b> | Compressor | <b>Yes</b> |

|   |        |
|---|--------|
| Total cost ex VAT   | 421,14 |
| Sill outer L, Scratch(es), LI - Repair and paint (complete) | 310,50 |



|                                  |        |
|----------------------------------|--------|
| Bumper R, Deformed, Smart repair | 110,64 |
|----------------------------------|--------|



|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>          |      |
| Front bumper, Scratch(es), Acceptable  | 0,00 |
| <i>No pictures to display</i>          |      |