



**OPEL Vivaro 2900: 1DOL444**

Vinnumber:	<b>WOLF7B0A6CV632231</b>	Versionname:	<b>VIVARO 2900 B/F L1H1 DPF (EU5) 90PK</b>
First Registrationdate:	<b>6/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>159113</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV05</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Rear parking sensors
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of Lining:	<b>Lining fabrics</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/65/16/106 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 2024,68

Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 362,02



Wing F R, Scratch(es), It - Spot repair 115,56



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,88



Bumper R, Bump(s) and scratch(es), E - Replace 329,40



Door moulding Lower R R, Accident, E - Replace 91,50



Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*

Fuel cap cover, Damaged, E - Replace 49,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15

