



BMW 1: 1FVA284

Vinnnumber:	WBA1C91090J518128	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	120227	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2108
Maintenance:	OCTOBER 2017		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining artificial leather	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	2490,23
-------------------	----------------

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable	0,00
-----------------------------------------------	-------------

No pictures to display


Tyre repair kit, Empty, E - Replace	210,53
-------------------------------------	---------------



Bumper grille, Broken, E - Replace 32,40



Front bumper, Scratch(es), LI - Repair and paint (complete) 307,80



Door R R, Scratch(es), LI - Repair and paint (complete) 438,35



Luggage space cover, Missing, E - Replace 240,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille F R, Broken, E - Replace 32,40



Seat F L compl, Worn, P - Check 0,00



Bumper grille, Broken, E - Replace 32,40



Bumper R, Scratch(es), LI - Repair and paint (complete) 259,80



Door R L, Bump(s), LI - Repair and paint (complete) 318,35



Wing R R, Damaged, LI - Repair and paint (complete) 428,20



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Wing F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
-----------------------------------------------	------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
-----------------------------------------------	------

No pictures to display