



BMW 5: 1GDJ727

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA5C11090D035417 | Versionname: | 5 BER 518d 136PK |
| First Registrationdate: | 7/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 71657 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2329 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------------|---------------------|-------|---------------------|
| | 225/55/17/101 H LightMetal | | | |
| Winter tyres: | Fr.L. | Kleber: 6 mm | Fr.R. | Kleber: 6 mm |
| | Re.L. | Kleber: 5 mm | Re.R. | Kleber: 5 mm |

Assistance equipment


| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 444,16 |
|-------------------|---------------|

| | |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|---------------|



| | |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



| | |
|---|-------------|
| Door F L, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|-----------------------------|------|
| Bonnet, Bump(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

| | |
|---------------------------|------|
| Roof, Bump(s), Acceptable | 0,00 |
|---------------------------|------|

No pictures to display