



<b>PEUGEOT 5008: 1EHW145</b>			
Vinnnumber:	<b>VF30A9HD8CS256075</b>	Versionname:	<b>5008 Allure FAP 115PK</b>
First Registrationdate:	<b>7/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>117279</b>	Power Kw:	<b>84</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2105</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			






















<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		





<b>Degree of wear</b>				
	<b>215/50/17/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>1720,09</b>
<b>Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)</b>			<b>115,56</b>



<b>Ceiling, Hole, Smart repair</b>	<b>64,32</b>
------------------------------------	--------------

Wing R R, Bump(s), Acceptable	0,00	
<i>No pictures to display</i>		
Door R R, Bump(s), PDR - Knock out without painting	63,00	
		
Gear shift lever knob, Worn, Acceptable	0,00	
<i>No pictures to display</i>		
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35	
		
Rocker panel inner R R, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00	
		
		
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80	
		
		
		
Door F R, Bump(s), PDR - Knock out without painting	63,00	
		
Wing F L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>		
Sill outer L, Bump(s), LI - Repair and paint (complete)	406,50	
		
Tailgate, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>		
Bonnet, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>		

Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Backrest cover F L, Damaged, E - Replace	109,00
	
Tailgate, Bump(s), PDR - Knock out without painting	63,00
	
Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), It - Spot repair	115,56
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	