



SKODA Octavia: 1EDF538			
Vinnumber:	TMBHT21ZXC2072075	Versionname:	OCTAVIA COMBI GTec Ambition DPF 105PK
First Registrationdate:	25/10/2012	Fiscalpower:	
Expertise Mileage:	212379	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2332
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	2928,08
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Interior, Dirty, Cleaning	25,00
---------------------------	-------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Windscreen, Repaired, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Bump(s), PDR - Knock out without painting 82,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Hole, Smart repair 64,32




Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), LI - Repair and paint (complete) 290,08



Rearview mirror housing R, Hole, E - Replace 64,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20

