



## VOLKSWAGEN PASSAT: 1GDK194

Vinnumber:	<b>WVWZZZ3CZEE088671</b>	Versionname:	<b>SEDAN</b>
First Registrationdate:	<b>8/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>95282</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2603</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	32,00
Wing R L, Bad repair, Paint	0,00



Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Bad repair, Paint	0,00



Door F L, Increased paint layer, No repair 0,00



Bonnet, Bad repair, Paint 0,00



Moulding windscreen L, Missing, E - Replace 32,00



Front bumper, Bad repair, I - Repair 0,00



Rearview mirror housing L, Stone chip(s), Acceptable 0,00

No pictures to display