


BMW 518D: 1JJG315

Vinnnumber:	WBA5L110X0D968825	Versionname:	5 TOURING 518dA 150PK Aut.
First Registrationdate:	2/01/2015	Fiscalpower:	
Expertise Mileage:	145902	Power Kw:	110
Bodytype:		Body color	Dark Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	14000 KM	Parking lot	3401
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS base	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 8 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	508,48
-------------------	--------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Backrest cover F L, Scratch(es), Smart repair	64,32
---	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Repaired, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable 0,00

No pictures to display

Xenon headlight R, Waterinfiltration, P - Check 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Xenon headlight L, Waterinfiltration, P - Check 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16

