



HYUNDAI H1: 1GGQ109			
Vinnumber:	KMFWBX7KADU538593	Versionname:	
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	123579	Power Kw:	100
Bodytype:	Transporter	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3118
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/70/16/108 T LightMetal			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	1868,42
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	165,13



Tailgate, Bump(s), LI - Repair and paint (complete)	362,02
---	---------------



Bumper R, Bump(s), Acceptable	0,00
-------------------------------	-------------

<i>No pictures to display</i>	
Wing R R, Bump(s), PDR - Knock out without painting	63,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Headlight R, Scratch(es), E - Replace 321,00



Front bumper, Hole, Le - Replace and paint 575,25



Sliding door L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02

