



DACIA Duster: 1CQK058			
Vinnumber:	UU1HSDACN46840058	Versionname:	DUSTER 4x4 Laureate FAP 109PK
First Registrationdate:	2/02/2012	Fiscalpower:	
Expertise Mileage:	115778	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2828
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	215/65/16/98 H LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT		1702,07	
Wing R R, Chemical polution, 67 - Polish		55,19	



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Roof, Chemical polution, 67 - Polish	55,19
--------------------------------------	-------




Side bar R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 356,20



Side bar L, Scratch(es), Acceptable 0,00

No pictures to display

Rear Panel Internal Lining, Scratch(es), Smart repair 110,64



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper grille, Broken, E - Replace 32,40



Seat cover R L, Stain, Cleaning 50,00



Bumper moulding F, Deformed, E - Replace 14,40



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

