


PEUGEOT Boxer 335: 1DXG834

Vinnumber:	VF3YCUMFB12288659	Versionname:	BOXER 335 B/F MWB HR L2H2 FAP 150PK
First Registrationdate:	25/09/2012	Fiscalpower:	
Expertise Mileage:	132450	Power Kw:	110
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2511
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1167,39
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Smart repair	110,64



Sill outer L, Scratch(es), It - Spot repair	115,56
---	--------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Interior, Dirty, Cleaning 100,00



Trunk door R L, Bump(s), Acceptable 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Internal Boot Lining R, Damaged, Smart repair 110,64



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Trunk door R R, Bump(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Smart repair 110,64

