


BMW 5: 1HUP176

Vinnumber:	WBA5E310X0D672581	Versionname:	5 BER 518d 136PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	178916	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2405
Maintenance:	AUGUSTUS 2019		
Maintenance:	5000		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 888,96

Bumper R, Damaged, LI - Repair and paint (complete) 0,00




Windscreen, Stone chip(s), Windscreen repair 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F R, Scratch(es), Paint 0,00



Bumper grille F R, Damaged, Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Damaged, Le - Replace and paint 0,00



Roof, Bump(s), PDR - Knock out without painting 142,20



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Sill outer R, Damaged, LI - Repair and paint (complete) 444,60



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 302,16



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Damaged, Acceptable 0,00

No pictures to display

Wing R R, Damaged, LI - Repair and paint (complete) 0,00

