



<b>FORD Focus: 1FEQ248</b>			
Vinnumber:	<b>WF0KXXGCBKDB65156</b>	Versionname:	<b>DIESEL</b>
First Registrationdate:	<b>7/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>129776</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3626</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
GPS storage	Rear parking sensors
GPS storage	<b>SD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS base</b>
Type of Lining	<b>Lining fabrics</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/55/16/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 8 mm</b>	Fr.R.	<b>Vredestein: 8 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>660,32</b>
<b>Wing F R, Bump(s), PDR - Knock out without painting</b>			<b>63,00</b>



<b>Door panel F L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------



<b>Wheel cover F R, Missing, E - Replace</b>	<b>30,00</b>
--	--------------



Wing R L, Scratch(es), 67 - Polish 55,19



Door R L, Scratch(es), 67 - Polish 55,19



Wing R R, Bump(s), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00



Bonnet, Scratch(es), 67 - Polish 55,19



Door R R, Scratch(es), Acceptable 0,00



Interior, Dirty, Cleaning 100,00



Roof pillar L, Bump(s), PDR - Knock out without painting 63,00



Boot cover, Broken, E - Replace 88,75

