



**FORD TRANSIT : 1DLQ164**

Vinnumber:	<b>WF05XXBDF5CG35759</b>	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	<b>285751</b>	Power Kw:	<b>74</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3704</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>6</b>		
Number head rests:	<b>6</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/70/15/104 R Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 1 mm</b>	Fr.R.	<b>Goodyear: 1 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	<b>1147,40</b>
Number plate light R, Damaged, E - Replace	<b>32,00</b>



Interior, Dirty, Cleaning	<b>150,00</b>
---------------------------	---------------



Door R L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Moulding windscreen R, Missing, Le - Replace and paint	<b>98,00</b>



Seat cover R L, Hole, E - Replace 300,00



Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Rearlight L tailgate, Damaged, E - Replace 120,00



Internal Boot Lining R, Damaged, Smart repair 110,64



Moulding windscreen L, Missing, Le - Replace and paint 98,00



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*