



AUDI A5: 1FLF671			
Vinnnumber:	<b>WAUZZZ8TXEA013854</b>	Versionname:	<b>A5 SB DPF Multitr. 136PK Aut.</b>
First Registrationdate:	<b>5/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>57672</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4829</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
GPS storage	<b>HD</b> Front parking sensors
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/50/17/91 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 2 mm</b>	Re.R.	<b>Bridgestone: 2 mm</b>

Assistance equipment	
Spare wheel	<b>Yes</b> Jack <b>Yes</b>
Total cost ex VAT	4254,00
Door R R, Bump(s), LI - Repair and paint (complete)	454,02



Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	--------



Wing R L, Bump(s), LI - Repair and paint (complete) 417,84



Front bumper, Crack, Le - Replace and paint 0,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 264,21



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F R, Bump(s), LI - Repair and paint (complete) 430,02



Bumper grille, Damaged, E - Replace 34,08



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 465,84





Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), Le - Replace and paint 0,00



Door frame F L, Damaged, E - Replace 74,00



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Bump(s), LI - Repair and paint (complete) 420,60



Door R L, Bump(s), LI - Repair and paint (complete) 382,02



Door F L, Bump(s), LI - Repair and paint (complete) 454,02



Roof pillar L, Scratch(es), It - Spot repair 115,56

