


SKODA Fabia BREAK: 1DXH706

Vinnnumber:	TMBJK25JXD3039520	Versionname:	FABIA COMBI GreenLine Ambition DPF 75PK
First Registrationdate:	25/09/2012	Fiscalpower:	
Expertise Mileage:	186884	Power Kw:	55
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1614
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	NOT OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			991,74
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Trunk lid covering R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Windscreen, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Interior, Dirty, Cleaning			100,00



Interior, Smell, Ozone treatment 152,58

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Bump(s) and scratch(es), LI - Repair and paint (complete) 176,14



Wing F L, Scratch(es), LI - Repair and paint (complete) 176,14



Bumper R, Bump(s), LI - Repair and paint (complete) 217,44



Door F R, Repaired, 67 - Polish 0,00

No pictures to display

Wing R R, Repaired, 67 - Polish 0,00

No pictures to display

Wing F R, Repaired, 67 - Polish 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Door R R, Repaired, 67 - Polish 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display