



BMW 3: 1GGR727

|                                   |                   |              |                  |
|-----------------------------------|-------------------|--------------|------------------|
| Vinnumber:                        | WBA3D11030F328724 | Versionname: | 3 BER 318d 136PK |
| First Registrationdate:           | 4/02/2014         | Fiscalpower: |                  |
| Expertise Mileage:                | 103843            | Power Kw:    | 100              |
| Bodytype:                         |                   | Body color   | Grey             |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic          |
| Transmission:                     |                   | Rims summer  | Aluminium        |
| Fueltype:                         | Diesel            | Oil level    | OK               |
| Battery functioning               | Yes               | Parking lot  | 1109             |
| Number of doors                   | 4                 |              |                  |
| Number of seats                   | 5                 |              |                  |
| Number head rests                 | 5                 |              |                  |
| Rims summer                       | Aluminium         |              |                  |
| Category                          | Passenger Car     |              |                  |
| Oil level                         | OK                |              |                  |
| Registration Certificate Car (BE) | Yes               |              |                  |

Options

|                                |                       |
|--------------------------------|-----------------------|
| Radio CD                       | Central consol F      |
| Windows electric F             | Rear parking sensors  |
| Windows electric R             |                       |
| Cruise Control                 |                       |
| Steering wheel multifunctional |                       |
| Radio multimedia               |                       |
| Type of headlighting           | Headlighting Halogen  |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining leather        |
| Type of climate control        | Autom climate control |

Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Sound engine        | OK  |
| Idle position       | OK | Clutch test         | OK  |
| Engine startingtime | OK | Wiper fluid level   | OK  |
| Exhaust gass        | OK | Lighting            | OK  |
| Transmission        | OK | Wiperblades         | OK  |
| Handbrake           | OK |                     |     |

Degree of wear

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
| Summer tyres: | 205/60/16/92 W LightMetal |                |       |                |
|               | Fr.L.                     | Goodyear: 3 mm | Fr.R. | Goodyear: 3 mm |
|               | Re.L.                     | Goodyear: 3 mm | Re.R. | Goodyear: 3 mm |

Assistance equipment

|                                                              |     |            |         |
|--------------------------------------------------------------|-----|------------|---------|
| Repair kit                                                   | Yes | Compressor | Yes     |
| Total cost ex VAT                                            |     |            | 1029,75 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |     |            | 95,00   |



|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Bump(s), Acceptable                           | 0,00   |
| No pictures to display                                  |        |
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35 |



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Front bumper, Scratch(es), Acceptable

0,00

No pictures to display