


MERCEDES A: 1ENB274

Vinnumber:	WDD1760121J027833	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	28/01/2013	Fiscalpower:	
Expertise Mileage:	171710	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3532
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1016,80
-------------------	----------------

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------

	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	Door R L, Scratch(es), Acceptable	0,00

No pictures to display