


MERCEDES A: 1GGO009

Vinnumber:	WDD1760121J232987	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	129182	Power Kw:	80
Bodytype:	Hatchback	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Steering wheel multifunction		Rear parking sensors	
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

25/45/17/91 H LightMetal				
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment








Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1580,15
-------------------	---------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
	Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	Ignition key, Missing, E - Replace	150,00

No pictures to display