



VOLVO V40: 1GDZ656

Vinnnumber:	YV1MZ8451E2040839	Versionname:	V40 Cr.Country D2 Base
First Registrationdate:	13/01/2014	Fiscalpower:	115PK
Expertise Mileage:	105924	Power Kw:	84
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

225/50/17/94 V LightMetal			
Summer tyres:	Fr.L. Michelin: 3 mm	Fr.R. Michelin: 3 mm	
	Re.L. Michelin: 3 mm	Re.R. Michelin: 3 mm	

Assistance equipment








Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1282,02
--------------------------	----------------

Front bumper, Scratch(es), It - Spot repair	115,56
--	---------------



Bumper R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>		
Bumper F R, Scratch(es), Smart repair		110,64
		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Headlight R, Broken, E - Replace		396,00
		
Ignition key, Missing, E - Replace		150,00
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Engine protective plate, Tear, E - Replace		84,00
		
Bumper moulding R, Bump(s) and scratch(es), Smart repair		110,64
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		