



**HYUNDAI i30: 1FSO511**

Vinnnumber:	<b>TMAD381UAEJ046212</b>	Versionname:	<b>i30 WAGON Blue Drive</b>
First Registrationdate:	<b>11/10/2013</b>	Fiscalpower:	<b>110PK</b>
Expertise Mileage:	<b>167335</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2305</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

**Assistance equipment**


Jack **Yes**

Total cost ex VAT **1836,46**

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) **95,00**



Bumper R, Scratch(es), LI - Repair and paint (complete) **211,80**





Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Headlight L, Damaged, E - Replace

396,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Bump(s), LI - Repair and paint (complete)

220,18




Wing R L, Bump(s), Acceptable

0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display