


BMW 318: 1JUL986

Vinnnumber:	WBA3K11030F837069	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	27/02/2015	Fiscalpower:	
Expertise Mileage:	171601	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2111
Maintenance:	PLUS 10000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm











Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	560,36
-------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Alloy rim R R, Scratch(es), Acceptable	0,00
	
Foglight L, Broken, E - Replace	138,00
	
Roof, Bump(s), Acceptable	0,00
	
Wing R L, Scratch(es), Acceptable	0,00
	
Wing R R, Bump(s), Acceptable	0,00
	
Windscreen, Stone chip(s), E - Replace	0,00
	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Roof pillar R, Bump(s), Acceptable	0,00
	
Door F L, Scratch(es), Acceptable	0,00
	
Bumper R, Scratch(es), It - Spot repair	115,56
	
Alloy rim F R, Scratch(es), Acceptable	0,00

