



VOLKSWAGEN Crafter 35 MWB: 539BVP			
Vinnnumber:	<b>WV1ZZZ2FZA7003947</b>	Versionname:	<b>CRAFTER 35 LB2C MWB 109PK</b>
First Registrationdate:	<b>12/07/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>246384</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV13</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

Options		
Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining artificial leather</b>	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>235/65/16/115 R Steel</b>			
Summer tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

Assistance equipment	
Spare wheel	<b>Yes</b>

Total cost ex VAT	<b>1855,48</b>
Windscreen, Repaired, Acceptable	<b>0,00</b>



Door F L, Rust, LI - Repair and paint (complete)	<b>238,76</b>
--	---------------



Sill outer L, Rust, LI - Repair and paint (complete)	<b>232,88</b>
--	---------------



Door F R, Rust, LI - Repair and paint (complete)	<b>238,76</b>
--	---------------

Door R, Rust, LI - Repair and paint (complete) 238,76



Interior, Dirty, Cleaning 150,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R L, Rust, LI - Repair and paint (complete) 238,76



Seat cover F L, Damaged, E - Replace 300,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,56



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display