



## VOLVO S80: 1EHW133

Vinnnumber:	<b>YV1AS88A0D1170411</b>	Versionname:	<b>S80 BER D4 Kinetic S/S Geartr.163PK Aut.</b>
First Registrationdate:	<b>7/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>154282</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2830</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>225/50/17/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

## Assistance equipment

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>1479,20</b>
-------------------	----------------

Alloy rim R L polished, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>369,84</b>
---	---------------



Alloy rim F R polished, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Wing R R, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), It - Spot repair 115,56



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Bump(s), Acceptable 0,00

No pictures to display

Door panel R R, Broken, E - Replace 132,00



Bumper R, Damaged, Le - Replace and paint 766,80

