


**OPEL Vivaro 2900: 1TTR139**

Vinnnumber:	<b>WOLF7B0A6CV632590</b>	Versionname:	<b>VIVARO 2900 B/F L1H1 DPF (EU5) 90PK</b>
First Registrationdate:	<b>6/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>81489</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV10</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Transmission	<b>OK</b>	Lighting	<b>OK</b>
Handbrake	<b>OK</b>	Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/65/16/104 R Steel</b>			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

**Total cost ex VAT** 618,65

**Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)** 165,13

**Bumper R, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Door moulding Lower R R, Scratch(es), E - Replace** 91,50

**Sliding door R, Bump(s), Acceptable** 0,00

*No pictures to display*
**Rearview mirror housing L, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)** 362,02



Bodywork, Not original part, Acceptable

0,00

*No pictures to display*