


AUDI A6: 1HTJ405

Vinnnumber:	WAUZZZ4G9EN194575	Versionname:	A6 AVANT Ultra 190PK
First Registrationdate:	29/09/2014	Fiscalpower:	
Expertise Mileage:	163379	Power Kw:	140
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/60/16/98 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1317,93
-------------------	----------------


Trunk lid covering R, Scratch(es), Acceptable	0,00
-----------------------------------------------	-------------

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
-------------------------------------------------------------------	---------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	0,00
-------------------------------------------------------------	-------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Damaged, E - Replace

0,00




Wing F R, Chemical pollution, LI - Repair and paint (complete)

264,21



Ceiling, Dirty, Cleaning

25,00



Certificate Of Conformity, Missing, E - Replace

150,00



Bumper F R, Scratch(es), LI - Repair and paint (complete)

0,00

No pictures to display

Alloy rim F L, Damaged, LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16





Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel arch cover F R, Missing, E - Replace	149,00
--------------------------------------------	--------



Interior, Dirty, Cleaning	75,00
---------------------------	-------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Backrest cover F L, Scratch(es), Acceptable	0,00
---------------------------------------------	------

No pictures to display