



FORD Mondeo: 1FRG647			
Vinnumber:	WF0GXXGBBGDG58614	Versionname:	MONDEO CLIP EConet.Titanium Style 115PK
First Registrationdate:	1/10/2013	Fiscalpower:	85
Expertise Mileage:	131217	Power Kw:	85
Bodytype:	MAN 6 VIT	Body color:	Silver
Gearbox:	Back	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3619
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	BF Goodrich: 6 mm	Re.R.	BF Goodrich: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			973,22
Door F L, Bump(s), PDR - Knock out without painting			82,80



Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Rust, LI - Repair and paint (complete)		290,08



Wing R L, Bump(s) and scratch(es), It - Spot repair 115,56



Roof, Hail damage, PDR - Knock out without painting 201,60



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s), PDR - Knock out without painting 63,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display