



| | | | |
|-------------------------|--------------------------|--------------|-------------------------------|
| AUDI A3: 1FBH379 | | | |
| Vinnumber: | WAUZZZ8V1DA051120 | Versionname: | A3 SB Attraction 105PK |
| First Registrationdate: | 15/05/2013 | Fiscalpower: | |
| Expertise Mileage: | 100743 | Power Kw: | 77 |
| Bodytype: | | Body color: | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2201 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

| | | | |
|-------------------------------------|------------|---------------------|------------|
| Limited Technical Inspection | | | |
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 205/55/16/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

| | | | |
|-----------------------------|------------|------------|------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |

| | |
|--|----------------|
| Total cost ex VAT | 2254,09 |
| Wing F L, Scratch(es), LI - Repair and paint (complete) | 220,18 |



| | |
|---|---------------|
| Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) | 115,56 |
|---|---------------|



| | |
|--|---------------|
| Rear window, Scratch(es), E - Replace | 370,00 |
|--|---------------|



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

