



CITROEN C4 Picasso: 1FKE634

Vinnnumber:	VF7UA9HR8DJ686004	Versionname:	GR.C4 PICASSO
First Registrationdate:	24/07/2013	Fiscalpower:	7pl.Seduct.FAP 112PK Aut
Expertise Mileage:	79909	Power Kw:	82
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2121
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Total cost ex VAT	1614,22
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bump(s), PDR - Knock out without painting

82,80



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), 67 - Polish 55,19



Wing F R, Scratch(es), 67 - Polish 55,19



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), 67 - Polish 55,19



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), It - Spot repair 115,56



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing R R, Scratch(es), 67 - Polish 55,19



Interior, Dirty, Forfeit 100,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display