


**OPEL INSIGNIA: 1GHZ826**

Vinnumber:	<b>WOLGM8ER8E1070435</b>	Versionname:	<b>INSIGNIA BRE ecoFLEX Edition 120PK</b>
First Registrationdate:	<b>13/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>179753</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2712</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 8 mm</b>	Fr.R.	<b>Goodyear: 8 mm</b>
	Re.L.	<b>Goodyear: 9 mm</b>	Re.R.	<b>Goodyear: 9 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	899,56
Tailgate, Bump(s), LI - Repair and paint (complete)	301,68



Bumper R, Deformed, LI - Repair and paint (complete)	307,80
--	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R polished, Rust, Acceptable	0,00
--	------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof rail R, Bump(s), Acceptable	0,00
----------------------------------	------

No pictures to display

Alloy rim F L polished, Rust, Acceptable	0,00
--	------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Windscreen, Bad repair, Acceptable	0,00
------------------------------------	------



Alloy rim R L polished, Rust, Acceptable	0,00
--	------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Alloy rim F R polished, Rust, Acceptable	0,00
--	------

