


BMW 3: 1EMW233

Vinnumber:	WBA3D91000F404270	Versionname:	3 BER 316d 116PK
First Registrationdate:	25/01/2013	Fiscalpower:	
Expertise Mileage:	166261	Power Kw:	85
Bodytype:	Berline	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3115
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment





Runflat	Yes
---------	------------





Total cost ex VAT	1346,50
Backrest cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper moulding F M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bonnet. Bad repair. Paint	0,00

		
		
Wing R R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Roof, Chemical polution, LI - Repair and paint (complete)		505,50

		
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00

		
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Bump(s) and scratch(es), Le - Replace and paint		651,00

