



VOLVO V40: 1GHH727			
Vinnumber:	YV1MV8481E2133526	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	128956	Power Kw:	84
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2603
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		











Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1318,35
Interior, Dirty, Cleaning			100,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------

	Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Bumper corner R R, Scratch(es), Acceptable	0,00

No pictures to display