



BMW 5: 1GWX400			
Vinnumber:	WBA5J11060D065805	Versionname:	5 TOURING 518dA 136PK Aut.
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	159158	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4304
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2022,04
Roof pillar L, Chemical polution, LI - Repair and paint (complete)			264,22



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), PDR - Knock out without painting	63,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rear window, Scratch(es), E - Replace

420,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00






Door R L, Bump(s), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

697,80



Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Boot carpet, Stain, Cleaning

25,00

