



## SEAT Alhambra: 1ESF855

Vinnnumber:	<b>VSSZZZ7NZDV513649</b>	Versionname:	<b>ALHAMBRA Eco.Tech.Styl.DPF DSG 136PK Aut</b>
First Registrationdate:	<b>7/03/2013</b>	Fiscalpower:	<b>100</b>
Expertise Mileage:	<b>117245</b>	Power Kw:	<b>100</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4822</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

<b>215/60/16/95 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

## Assistance equipment

Total cost ex VAT	3111,02
Wing R R, Chemical polution, LI - Repair and paint (complete)	369,84



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tyre repair kit, Missing, E - Replace	252,64



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 420,00



Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Door panel R L, Tear, E - Replace 156,00



Interior, Stain, Cleaning 50,00



Bonnet, Bad repair, Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Rear Panel Internal Lining, Damaged, E - Replace 133,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Windscreen, Stone chip(s), E - Replace 560,64



Rocker panel inner R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Centre console, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Door panel F L, Dirty, Acceptable	0,00
<i>No pictures to display</i>	
Moulding windscreen L, Damaged, E - Replace	88,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

