



PEUGEOT 508SW: 1FBT388			
Vinnnumber:	VF38E9HL0DL024317	Versionname:	1.6 HDI SW Active 115PK
First Registrationdate:	17/05/2013	Fiscalpower:	
Expertise Mileage:	197798	Power Kw:	84
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1525
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Panoramic roof
GPS storage	Central consol F
GPS storage	HD Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	215/60/16/99 H LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1092,02
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)			310,50



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F L, Worn, Smart repair 64,32



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Engine protective plate, Tear, E - Replace	74,00

