



RENAULT Scenic: 1EHU007

Vinnumber:	VF1JZ140648174762	Versionname:	SCENIC Energ.Business
First Registrationdate:	6/12/2012	Fiscalpower:	110PK
Expertise Mileage:	102044	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3222
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3004,16
-------------------	---------

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper corner R R, Scratch(es), LI - Repair and paint (complete)	0,00
--	------



Wheel arch cover F R, Missing, E - Replace 0,00



Bumper grille F R, Broken, E - Replace 32,40

No pictures to display

Boot cover, Missing, E - Replace 50,00

No pictures to display

Reflector, Broken, E - Replace 0,00



Interior, Stain, Chemical cleaning 0,00



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bodywork, Not original part, Remove lettering 0,00

No pictures to display

Wing F L, Scratch(es), It - Spot repair 115,56



Sill outer R, Bump(s), LI - Repair and paint (complete) 310,50

No pictures to display

Door F L, Bump(s), LI - Repair and paint (complete) 318,35



Rocker panel inner R R, Scratch(es), Acceptable 0,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Broken, Le - Replace and paint 735,00



Fuel cap cover, Missing, Le - Replace and paint 0,00



Bumper R, Deformed, E - Replace 415,20

No pictures to display

Bumper corner R L, Scratch(es), LI - Repair and paint (complete) 0,00

No pictures to display

Bumper grille, Broken, E - Replace 32,40



Wheel cover F R, Scratch(es), E - Replace 30,00

