



## VOLVO V70: 1GAU170

Vinnnumber:	<b>YV1BW88A1E1297758</b>	Versionname:	<b>V70 D4 Kinetic 163PK</b>
First Registrationdate:	<b>10/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>136918</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1508</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L
Windows electric F		Seats electric F R
Windows electric R		Seats F L ventilated
Cruise Control		Seats F R ventilated
Steering wheel multifunctional		Sun Roof electric
Seats F heated		Central consol F
Radio multimedia		Luggage cover
Type of headlighting:	<b>Headlighting Xenon</b>	Rear parking sensors
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining leather</b>	
Type of climate control:	<b>Autom climate control</b>	

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 1010,34

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 279,16



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Rust, Acceptable	0,00
--	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------

