



VOLVO V70: 1EKR984			
Vinnumber:	YV18W31A1D1262953	Versionname:	V70 D3 Kinetic St/St 136PK
First Registrationdate:	8/01/2013	Fiscalpower:	
Expertise Mileage:	161871	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4119
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	2553,43
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 264,21



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



