


SKODA Octavia: 1DST160

Vinnnumber:	TMBHT21Z5D2038045	Versionname:	OCTAVIA COMBI GTec Ambition DPF 105PK
First Registrationdate:	14/08/2012	Fiscalpower:	
Expertise Mileage:	211514	Power Kw:	77
Bodytype:	Break	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4427
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/95 T LightMetal			
Winter tyres:	Fr.L.	Firestone: 1 mm	Fr.R.	Firestone: 1 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2567,80
-------------------	---------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------













Sill outer R, Bump(s) and scratch(es), Le - Replace and paint	0,00
---	------



Registration Document, Missing, E - Replace	150,00
---	--------

No pictures to display

Interior, Dirty, Cleaning	50,00
---------------------------	-------

		
		
Backrest cover F L, Worn, Acceptable		0,00
		
Door R L, Scratch(es), LI - Repair and paint (complete)		318,35
		
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		0,00
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)		301,68
		
Bonnet, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
		
Door F R, Scratch(es), LI - Repair and paint (complete)		0,00
		
Wing R R, Scratch(es), LI - Repair and paint (complete)		0,00
		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Rear window, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Luggage space cover, Missing, E - Replace		240,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Bump(s) and scratch(es), Le - Replace and paint 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

