



AUDI A3: 1ESM071			
Vinnnumber:	WAUZZZ8V9DA036011	Versionname:	A3 SB Ambiente 150PK
First Registrationdate:	8/03/2013	Fiscalpower:	
Expertise Mileage:	132550	Power Kw:	110
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3325
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
GPS storage SD	Central consol F
GPS storage	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting Headlighting Xenon	
Type of GPS GPS big screen color	
Type of Lining Lining leather and alcantara	
Type of climate control Autom climate control	







Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment	
Emergency spare wheel	Yes Jack Yes
Total cost ex VAT	1584,96
Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Door F R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Chemical polution, LI - Repair and paint (complete)	308,20

		
Door R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Chemical polution, LI - Repair and paint (complete)		481,50
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Roof pillar L, Chemical polution, LI - Repair and paint (complete)		220,18
		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Window F L door, Scratch(es), E - Replace		0,00
		
Luggage space cover, Not functioning (well), Acceptable		0,00
		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
