



VOLKSWAGEN Sharan: 1GFU882			
Vinnumber:	WVWZZZ7NZEV014765	Versionname:	SHARAN Trendline BMT
First Registrationdate:	28/01/2014	Fiscalpower:	136PK
Expertise Mileage:	150235	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/60/16/96 H Steel			
	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment	
Total cost ex VAT	1551,29
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	348,09



Wheel cover F L, Missing, E - Replace	36,00
---------------------------------------	-------



Wheel cover F R, Missing, E - Replace 36,00



Interior, Dirty, Cleaning 25,00




Wing R R, Bump(s), PDR - Knock out without painting 63,00



Ceiling, Stain, Cleaning 25,00

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02




Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Rear window, Scratch(es), Acceptable 0,00

No pictures to display