


BMW 3: 1GCY696

| | | | |
|-----------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | WBA3Y11050D448265 | Versionname: | 3 GRAN TURISMO 318d |
| First Registrationdate: | 3/01/2014 | Fiscalpower: | 136PK |
| Expertise Mileage: | 66203 | Power Kw: | 100 |
| Bodytype: | | Body color | Light Brown |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | NOT OK | Parking lot | 1333 |
| Maintenance | 1/01/2018 | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|----------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/101 V LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 6 mm | Fr.R. | Goodyear: 6 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | | |
|--------------------------------------|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 30,00 |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Sill trim L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Sill trim R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Maintenance, Maintenance, Execute | | | 0,00 |



| | |
|--|-------|
| Mirror side blinker R, Broken, E - Replace | 30,00 |
|--|-------|



| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-------------------------------------|------|
| Door panel R L, Damaged, Acceptable | 0,00 |
|-------------------------------------|------|

No pictures to display

| | |
|---|------|
| Wing R L, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display