



BMW 1: 1EQW602			
Vinnnumber:	WBA1N310X0J710665	Versionname:	1 SPORTSHATCH 116d Eff.Dyn.Ed.116PK
First Registrationdate:	26/02/2013	Fiscalpower:	
Expertise Mileage:	98654	Power Kw:	85
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4503
Number of doors:	3		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm






Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		741,00	
Alloy rim F L, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Windscreen, Damaged, E - Replace		0,00	



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Wing F R, Bump(s), Acceptable	0,00
-------------------------------	------

<i>No pictures to display</i>		
Door F R, Bump(s), PDR - Knock out without painting		63,00
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door F L, Bump(s), PDR - Knock out without painting		63,00
		
Wing F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		