



BMW 1: 1GEH048

Vinnnumber:	WBA1C91050J518823	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	15/01/2014	Fiscalpower:	
Expertise Mileage:	114647	Power Kw:	85
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4328
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1115,34

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display



Door F L, Bad repair, Paint 0,00





Wing R R, Bad repair, Paint 0,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 176,14



Roof, Scratch(es), LI - Repair and paint (complete) 385,20



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Door R R, Bump(s), PDR - Knock out without painting 63,00




Interior, Stain, Cleaning 75,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Paint 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Door R L, Scratch(es), Acceptable

0,00

No pictures to display