


MERCEDES C: 1GHI059

Vinnumber:	WDD2042021G263912	Versionname:	C BRE 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	59082	Power Kw:	120
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4404
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	960,39
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper moulding F L, Damaged, E - Replace 14,40



Backrest cover R M, Damaged, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Headlight R, Scratch(es), I - Repair 24,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Stone chip(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Roof, Stain, 67 - Polish 55,19

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



