


FORD Grand C-Max: 1DUA240

| | | | |
|-------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WF0HXXWPBHCD16989 | Versionname: | GR.C-MAX Titanium St/St |
| First Registrationdate: | 28/08/2012 | Fiscalpower: | 115PK |
| Expertise Mileage: | 149487 | Power Kw: | 85 |
| Bodytype: | Hatchback | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3508 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Seats electric F L |
| GPS storage | Central consol F |
| GPS storage | SD Luggage cover |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/97 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 764,04 |
|-------------------|--------|

| | |
|---|--------|
| Door R R, Chemical polution, LI - Repair and paint (complete) | 382,02 |
|---|--------|



| | |
|------------------------------------|------|
| Spoiler R, Scratch(es), Acceptable | 0,00 |
|------------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Roof, Scratch(es), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|---|--------|
| Door R L, Scratch(es), LI - Repair and paint (complete) | 382,02 |
|---|--------|



| | |
|--|------|
| Rear bulkhead lining, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |