


**RENAULT Captur: 1GCS496**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:                        | <b>VF12R5A1H49949158</b> | Versionname: | <b>CAPTUR Energy Zen 90PK</b> |
| First Registrationdate:            | <b>2/01/2014</b>         | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>40316</b>             | Power Kw:    | <b>66</b>                     |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Dark Grey</b>              |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Petrol</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2101</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                               |                      |
|--------------------------------|-------------------------------|----------------------|
| Windows electric F             | Central consol F              |                      |
| Windows electric R             | Luggage cover                 |                      |
| Cruise Control                 | Rear parking sensors          |                      |
| Steering wheel multifunctional | Type of Tow bar               | <b>Tow bar fixed</b> |
| Radio multimedia               |                               |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |
| Type of GPS                    | <b>GPS big screen color</b>   |                      |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |
| Type of climate control        | <b>Manual climate control</b> |                      |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |


**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/96 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|   |                |
|---|----------------|
| Total cost ex VAT                         | <b>1449,78</b> |
| Door panel R L, Scratch(es), Smart repair | <b>110,64</b>  |



|  |              |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



|  |              |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



|  |       |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|  |       |
|--|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|   |        |
|---|--------|
| Front bumper, Scratch(es), Smart repair | 110,64 |
|---|--------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



|   |        |
|---|--------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



|   |        |
|---|--------|
| Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|

